




130 Range

GEN₂ - 2130

GEN₂ - 3130


GEN₂ - 4130



GEN₂ - 6130

GEN₂ - 8130


GEN₂ - 10130

GEN₂ - 12130





Control tubing and wiring is not shown



7.4 process diagram

Note:

Letters surrounded by a red ring are reference to the required service kit for that component.

Service A: Replace exhaust silencer(s)/ muffler(s)


Service B: Replace piston valve seals



Service C: Replace all pilot valves, diaphragm valves and solenoid coils and oxygen analyser control valve(s)

Service D: Replace oxygen analyser(s)


For more information about service kits see page 7.



For more information about service schedules and prices please contact your service provider.






Pressure will build due to the CMS, expect loud releases of low pressure, high volume gas







Atmospheric Oxygen degrades the sensor